








機種	号機	年式
SK200-10	YN15-80848	2018

稼働時間	シュー	整備レベル
2,506	600 鉄	B





仕様	出展地
N&B/CR	東北支社



機種	号機	年式
SK200-10	YN15-80848	2018

稼働時間	シュー	整備レベル
2,506	600 鉄	B

仕様	出展地
N&B/CR	東北支社



機種	号機	年式
SK200-10	YN15-80848	2018

稼働時間	シュー	整備レベル
2,506	600 鉄	B

仕様	出展地
N&B/CR	東北支社

